<u> </u>							
1. TASK NUMBER			2.INVESTIGATOR'S ID				
960220CCC7028 X9G21484			8516		EPIDEMIOLOGIC		
3. OFFICE CODE	4. DATE OF ACCIDENT		5. DATE INITIATED		INVESTIGATION REPORT		
896	YR MO DAY 95 11 0 €			O DAY 02 20	REPORT		
6. SYNOPSIS OF ACCIDENT OR COMPLAINT The consumer placed two pieces of bread into a kitchen toaster oven for about 3-5 minutes. While in her dining room, she smelled an odor, walked into her kitchen and saw flames being emitted from the toaster oven. She extinguished all the flames with a towel and pulled the plug. There were no injuries and no property damage.							
7.LOCATION (Home, School, etc.)		8. CITY			9.STATE		
Home 10		M s Clean			Virginia Va.		
10A. FIRST PRODUCT Toaster oven 0216		10B. TRADE/BRAND NAME Black & Decker			10C. MODEL NUMBER TRO 600		
10D. MANUFACTURER NAME AND ADDRESS Black & Decker, Address Unk.							
11A. SECOND PRODUCT 11B. TRA			DE/BRAND NAME		11C. MODEL NUMBER		
6FCI 4063 Unk.			k.		Unk.		
11D. MANUFACTURER NAME AND ADDRESS Unk.							
12. AGE OF VICTIM	13. SEX		14. DISPOSITION		15. INJURY DIAGNOSIS		
No Injury 99	No Injury 0 No Injury 70						
16. BODY PART (S) INVOLVED	17.RESPONDENT		18. TYPE OF INVESTIGATION		19. TIME SPENT (OPERATIONAL HOURS)		
No Injury 99	Owner/User 1		Telephone 2		05.0		
20. ATTACHMENT(S)	21.CASE SOU	RCE		22. SAMPLE COLLECTION NUMBER			
None	Consumer	Referral	07	07 N/A			
23. PERMISSION TO DISCLOSE NAMES (NON NEISS CASES ONLY) YES NO XX							
24. REVIEW DATE	25. REVIEWE	D BY		l	L OFFICE DIRECTOR		
27. DISTRIBUTION				<u></u>			

PRE-ACCIDENT

This toaster oven was purchased approximately two years prior to the accident. The consumer said that she had read and understood the instructions (now discarded) for the toaster oven. It was always used in this single family house, where the accident happened. The toaster oven was kept and used in the kitchen of the house. It was used about five times per week; each time of use was for five minutes or less. It was primarily used to cook breakfast foods such as toast or bagels. It was used by the consumer and her two children.

The toaster oven was unplugged after every use. It was never used with an extension cord, surge protector or outlet multiplying adapter. When in use it was connected to a duplex GFCI protected outlet, in the kitchen. The consumer said that she kept the toaster oven away from the kitchen wall, when in use and made sure that there was no other combustible material around the toaster oven when in use.

She said that, prior to this accident, the toaster oven always worked correctly. The toast lever always returned to the "up" setting, after the toast was toasted. There were no problems with the way it cooked the food. She said that she never had to recycle the toast or other food to make sure that it cooked properly. The consumer said, that prior to this accident, while using the toaster oven, there was never any evidence of any sparks, smoke, flames or overheating. Before this accident, there were never odd sounds or odors from the toaster oven. It never caused any electrical shocks. Prior to the incident, there was no reason to believe it was malfunctioning in any way. She had never had any problems with the electrical outlets or wiring in this house.

The toaster oven was never modified of repaired, prior to the incident. It was never dropped or abused, during ownership. The consumer said that the crumb tray was cleaned about once per week. It was wiped clean with a damp paper towel. The toaster oven was never immersed in water or sprayed with water. It was occasionally wiped clean with a sponge. When the toaster oven was used, the consumer said that she made certain that the kitchen counter area around the oven was dry.

ACCIDENT

The accident happened in the morning, in approximately November, 1995. The toaster oven was connected to the duplex outlet; nothing else was connected to this outlet. No other appliance was being used, at the time.

960220CCC7028 Page 3

ACCIDENT (continued)

The consumer placed two slices of bread in the oven compartment in order to toast them. She then closed the oven door. The consumer pushed down the toast lever on the right hand side of the toaster oven, which activated the toast function. The toast color setting was turned "a little to the right of center". The consumer then walked into the dining room to set the dining room table, which was about five feet from the kitchen toaster oven. While in the dining room, she smelled the odor of something burning. At this point, the toast had been in the toaster oven from 3-5 minutes. Because of the burning odor, she walked into the kitchen.

As soon as she walked into the kitchen, she saw that orange colored flames were being emitted from the right front section of the closed door of the toaster oven. She said that the flames were several inches in length. Nothing else was burning, except the toaster oven. The consumer stated that it "registered in her mind" that the toast lever, on the side of the toaster oven was still in the "down" position, at the time of this fire.

She said that she took a cloth dish towel and "wacked out" the flames and pulled the power plug from the electrical outlet. She said that these actions completely extinguished the flames. During this time there was some smoke in the kitchen and a hall smoke alarm, that was about ten feet away, began sounding. She then opened a kitchen window to clear the smoke. The activity of seeing the burning toaster oven and extinguishing the flames took less that one minute.

POST ACCIDENT

There were no injuries involved in this accident. Other than the toaster oven, there was no property damage. Nothing else in the kitchen ignited. The fire department was not called and the insurance company was not notified. She examined the toaster oven after the fire but did not look inside the oven. She said that the door handle was now loose and the door did not fit correctly in the frame. There was melted plastic on the right side of the toaster oven. She said that the window for the oven door had not shattered, but it may have cracked; it was in one piece. The window was now discolored.

The toaster oven was discarded within the same week of this accident. The consumer did not contact the retailer or manufacturer about this incident.

960220CCC7028 Page 4

PRODUCT IDENTIFICATION/INFORMATION

As stated previously, the consumer discarded the toaster oven within a week after the fire in about November, 1995. The following are details, related by the consumer, about the toaster oven.

It was a Black and Decker brand toaster oven, model number "TRO 600". It had three controls on the right side of the toaster oven, an oven temperature setting dial (with bake and broil settings), a toast darkness setting and an up-down vertical slide lever to activate toasting for the toaster function.

It was made of chrome metal and plastic. It was front loading, with a pull down door on the front of the toaster oven. The door had a glass-type window.

STANDARDS INFORMATION

Unk.

EXHIBIT DESCRIPTION

N/A

ACCIDENT INVESTIGATION REQUEST FORM

Document Number X967	. 1484H						
Date of Incident Ful, 199	5 Category I.D. <u>SECT5</u> I 1996						
Follow-Up Requested	Hazard Analysis Section 15						
Type Follow-Op Requested	Telegraphic office on-site						
Readquarters Contact Jeanne M. Siehelt							
Assignment Message Please intervieur Commissiony							
	the incident with						
her Black + Dicker toaster oven. Please							
confirm details of incident findluding one							
exact date of the	e. medent). and						
determine exact	Model rumbe.						
	- and r						
	DO, pfice-						
	aton						
Person(s) to contact Jeanne M. Sieberk							
CAL							
	•						
Guideline Plase Call	me fiest - I have already						
done a preliminary	interview and would like to						
give you some backing	ound intolemation.						
Requested By J. Jichus 504							
Task Number 960220CCC							
Assigned to MASC	Date 2/20/96						
.	1 /						

CONSUMER PRODUCT INCIDENT REPORT

NAME OF RESPONDENT	2. TELEPHONE NO. (Home) (Work)
POPRESS	4. CITY STATE 21 CODE
The second control of	my Betresda, MD 20814
DESCRIBE ACCIDENT SITUATION OR HAZARD, INCLUDING DATA ON	WUURIES. (Use second page if necessary.)
Toashing 3 slices of B	HAd. Thasty lura
loasting 5 siles of	Year of the Control o
ded not come up. Unit	remained or 1 to
extended exceed of tim	ne escaping from one dock.
2 made in the good flar	ne escaping from the dock.
respondent actions	d extinguished Rice with towel
	1. IF VICTIM DIFFERENT FROM RESPONDENT, PROVIDE
DATE OF 7- IF INJURY OR REAR MISS COLORS INCIDENT(S)	
INCIDENT(S) AGE SEX AND I SEX INJURY	RELATIONSHIP
DESCRIPTION OF PRODUCT	10. BRAND NAME
Black + Decker Touster Oven	Black + Decker
1. MANUFACTURER/DISTRIBUTOR NAME, ADDRESS & PHONE	12. MODEL SERIAL NO.'S
6 Armstrong	unknown
Shelten, CT	13. DEALER'S NAME, ADDRESS & PHONE
Sillian, Ci	
	15. PRODUCT PURCHASED NEW USED
YES NO IF YES, BEFORE OR AFTER THE	DATE PURCHASED FOIL 1994 AGE 2 YES
Describe plashe melted, lever wow	d 18. DOES PRODUCT HAVE WARNING LABELS?
Not Land up	IF SO, NOTE:
17. HAVE YOU CONTACTED THE MANORACTORS	12 IS THE PRODUCT STILL AVAILABLE? 19. MAY WE USE YOUR NAME WITH THIS REPORT?
YES NO IF NOT, DO 100 100 100 100	YES NO YES NO IF NOT, ITS DISPOSITION
CONTACT THEM? YES NO	Distanded
FOR	ADMINISTRATION USE
Jan 76, 1996 Jeanne Sid	best , CAL X 962 1484
0041124 11114	162 1404
22. FOLLOWUP ACTION	24. PRODUCT CODE(S)
960220CCC 7028	216
25. DISTRIBUTION	28. ENDORSER'S NAME & TITLE
CPSC FORM 175 (9/89)	